



UTTAR PRADESH MEDICAL SUPPLIES CORPORATION LTD.

Regd. Office: SUDA Bhawan, 7/23, Sector-7, Gomti Nagar Extension, Lucknow-226 010

Ph: 0522 2838102 e-mail: drugs@upmsc.in

Result of Technical and Sample Evaluation of Expression Of Interest for PPE – Coverall Dated: 22.08.2020

S. No	Name of firm/ Supplier	Technically Qualified/ Not qualified	Reason for technical disqualification	Sample submission status	Sample evaluation result	Reason for Sample disqualification	Final result (based on Technical and Sample Evaluation)
1	72 Networks Pvt Ltd	Eligible	-	Received	Pass	-	Pass
2	AARNA GARMENTS	Eligible	-	Received	Pass	-	Pass
3	Amit gramodyog india	Not – Eligible	- No Technical Documents submitted by the firm	Received	Fail	- Coverall and shoe cover permeable at seam	Fail
4	Anand International	Eligible	-	Received	Fail	- Seams are not thermally taped - Shoe cover small in size and not easy to wear	Fail
5	Anitha Texcot	Not – Eligible	- Test certificate form govt. authorized laboratories is not submitted	Received	Fail	- Thumb/finger loop not present in sleeves	Fail
6	Bangar Business Ventures	Eligible	-	Received	Fail	- Coverall and shoe cover permeable at seam - Thumb/finger loop not present in sleeves	Fail
7	BMA PRINTS PVT LTD	Eligible	-	Received	Fail	- Thumb/finger loop not present in sleeves - Shoe cover	Fail

S. No	Name of firm/ Supplier	Technically Qualified/ Not qualified	Reason for technical disqualification	Sample submission status	Sample evaluation result	Reason for Sample disqualification	Final result (based on Technical and Sample Evaluation)
						permeable at seam	
8	Brontes Fire Private Limited	Not – Eligible	- No Technical Documents submitted by the firm - UTR no is not identified	Not – Received	-	-	Fail
9	C.S.GARMENTS	Eligible	-	Received	Fail	- Coverall and shoe cover permeable at seam	Fail
10	City Life Technologies Pvt Ltd	Not – Eligible	UTR no is not identified	Not – Received	-	-	Fail
11	Crea	Not – Eligible	- Manufacturing License not submitted UTR no is not identified	Not – Received	-	-	Fail
12	Crea Marketing Services	Not – Eligible	- Manufacturing License not submitted UTR no is not identified	Not – Received	-	-	Fail
13	Deeman Exim	Eligible	-	Received	Pass	-	Pass
14	Dollar Apparels	Eligible	-	Received	Fail	- Coverall permeable at seam	Fail
15	DONEAR INDUSTRIES LIMITED	Eligible	-	Received	Fail	- Shoe cover permeable at seam - Seams are not thermally taped in shoe cover - Shoe cover	Fail

S. No	Name of firm/ Supplier	Technically Qualified/ Not qualified	Reason for technical disqualification	Sample submission status	Sample evaluation result	Reason for Sample disqualification	Final result (based on Technical and Sample Evaluation)
						small in size and not easy to wear	
16	E febsew	Not – Eligible	- No Technical Documents submitted by the firm	Received	Fail	- Shoe cover permeable at seam	Fail
17	EquIndia	Not – Eligible	- No Technical Documents submitted by the firm UTR no is not identified	Not – Received	-	-	Fail
18	eYantra Industries Pvt Ltd	Not – Eligible	- No Technical Documents submitted by the firm	Received	Fail	- Shoe cover permeable at seam	Fail
19	Fifth Avenue Event Management	Eligible	-	Received	Pass	-	Pass
20	FOXBase	Not – Eligible	- No Technical Documents submitted by the firm - UTR no is not identified	Not – Received	-	-	Fail
21	GANESH MEDICAL EQUIPMENTS	Eligible	-	Received	Fail	- Coverall and shoe cover permeable at seam	Fail
22	Geetha Garments	Eligible	-	Received	Pass	-	Pass
23	Gkem International	Eligible	-	Received	Pass	-	Pass
24	Green Packaging	Eligible	-	Received	Pass	-	Pass
25	Hamraz International	Eligible	-	Received	Fail	- Thumb/finger loop not present in	Fail

S. No	Name of firm/ Supplier	Technically Qualified/ Not qualified	Reason for technical disqualification	Sample submission status	Sample evaluation result	Reason for Sample disqualification	Final result (based on Technical and Sample Evaluation)
						sleeves - Seams are not thermally taped - Shoe cover permeable at seam	
26	Hanuman Knit Fashion	Eligible	-	Received	Pass	-	Pass
27	Hi Tech International	Not – Eligible	- Manufacturing License submitted is not for PPE – Coverall - UTR no is not identified	Not – Received	-	-	Fail
28	India Trading Corporation	Eligible	-	Received	Fail	- Shoe cover permeable at seam	Fail
29	Innvolution Healthcare Pvt. Ltd	Eligible	-	Received	Pass	-	Pass
30	Invoke Medical System Pvt. Ltd	Not – Eligible	- Manufacturing License submitted is not for PPE – Coverall - UTR no is not identified	Not – Received	-	-	Fail
31	Kanons Overseas Ltd	Not – Eligible	- No Technical Documents submitted by the firm	Received	Pass	-	Fail
32	Kansons Group	Not – Eligible	- No Technical Documents submitted by the firm - UTR no is not	Not – Received	-	-	Fail

S. No	Name of firm/ Supplier	Technically Qualified/ Not qualified	Reason for technical disqualification	Sample submission status	Sample evaluation result	Reason for Sample disqualification	Final result (based on Technical and Sample Evaluation)
			identified				
33	Karigar Niryat Pvt. Ltd.	Eligible	-	Received	Pass	-	Pass
34	Kisnet	Not – Eligible	- No Technical Documents submitted by the firm - UTR no is not identified	Not – Received	-	-	Fail
35	Krishna incorporation	Not – Eligible	- Test certificate form govt. authorized laboratories is not in the name of bidder	Received	Fail	- Thumb/finger loop not present in sleeves - Shoe cover permeable at seam - Seams of shoe cover are not thermally taped	Fail
36	Lakeland Gloves	Eligible	-	Received	Pass	-	Pass
37	Loften India Pvt Ltd	Eligible	-	Received	Pass	-	Pass
38	Lyallpur Uniforms	Eligible	-	Received	Fail	- Seams of shoe cover and body cover are not thermally taped - Coverall and shoe cover permeable at seam - Shoe cover small in size and not easy to wear	Fail
39	Med Freshe Pvt. Ltd	Eligible	-	Received	Fail	- Shoe cover permeable at	Fail

S. No	Name of firm/ Supplier	Technically Qualified/ Not qualified	Reason for technical disqualification	Sample submission status	Sample evaluation result	Reason for Sample disqualification	Final result (based on Technical and Sample Evaluation)
						seam	
40	Medevice	Not – Eligible	- No Technical Documents submitted by the firm - UTR no is not identified	Not – Received	-	-	Fail
41	Real Ratna Fashion Pvt. Ltd	Eligible	-	Received	Pass	-	Pass
42	Richa Global Exports Pvt. Ltd.	Not – Eligible	- Manufacturing License submitted is not for PPE – Coverall	Received	Fail	- Shoe cover permeable at seam	Fail
43	S&D CONNEXIONS	Eligible	-	Received	Pass	-	Pass
44	SAI SYNERGY LLP	Not – Eligible	- No Technical Documents submitted by the firm - UTR no is not identified	Not – Received	-	-	Fail
45	Sakthi Infra Tex Private Limited	Eligible	-	Received	Pass	-	Pass
46	Sanjeev Bags	Eligible	-	Received	Fail	- Thumb/finger loop not present in sleeves - Shoe cover permeable at seam - Seams are not thermally taped in shoe cover	Fail
47	SANMATI PACKAGING	Eligible	-	Received	Pass	-	Pass
48	Sara International	Eligible	-	Received	Pass	-	Pass

S. No	Name of firm/ Supplier	Technically Qualified/ Not qualified	Reason for technical disqualification	Sample submission status	Sample evaluation result	Reason for Sample disqualification	Final result (based on Technical and Sample Evaluation)
49	Savitridevi Polyfabrics India Pvt. Ltd	Eligible	-	Received	Pass	-	Pass
50	Shiva Textfabs Limited	Eligible	-	Not – Received	-	-	Fail
51	Shrishriji Medisys	Not – Eligible	- Manufacturing License not submitted	Not – Received	-	-	Fail
52	SND INC	Eligible	-	Received	Pass	-	Pass
53	Sogo Fashions Private Limited	Eligible	-	Received	Pass	-	Pass
54	Sri Sai Ram Enterprises	Eligible	-	Received	Pass	-	Pass
55	Statice Energy Pvt Ltd	Eligible	-	Received	Fail	- Size of coverall is not universal fit - Seams of shoe cover are not thermally taped	Fail
56	SwamiTextiles	Not – Eligible	- Manufacturing License not submitted	Received	Pass	-	Fail
57	Swastik Value Addition Pvt Ltd	Eligible	-	Received	Pass	-	Pass
58	Synpak	Eligible	-	Received	Fail	- Shoe cover permeable at seam	Fail
59	THE BROOKS INTERNATIONAL	Eligible	-	Received	Fail	- Seams of shoe cover are not thermally taped - Shoe cover small in size and not easy to wear	Fail
60	Track Manufacturing Co.	Not – Eligible	- Manufacturing License	Received	Fail	- Thumb/finger loop not	Fail

S. No	Name of firm/ Supplier	Technically Qualified/ Not qualified	Reason for technical disqualification	Sample submission status	Sample evaluation result	Reason for Sample disqualification	Final result (based on Technical and Sample Evaluation)
	Pvt. Ltd.		submitted is not for PPE – Coverall			present in sleeves - Shoe cover permeable at seam - Seams of shoe cover are not thermally taped	
61	TRADITION GLOBE TRADE INDIA	Not – Eligible	- UTR no is not identified	Received	Fail	- Coverall and shoe cover permeable at seam - Shoe cover small in size and not easy to wear	Fail
62	United Exim	Not – Eligible	- Manufacturing License submitted is not for PPE – Coverall	Received	Fail	- Shoe cover permeable at seam	Fail
63	Unity Healthcare	Eligible	-	Received	Fail	- Thumb/finger loop not present in sleeves - Shoe cover permeable at seam and fabric	Fail
64	Uttam fashion	Not – Eligible	- Manufacturing License not submitted	Not – Received	-	-	Fail
65	Vastra Fashions	Eligible	-	Received	Pass	-	Pass
66	Vikram Nuvotech	Eligible	-	Received	Pass	-	Pass
67	VISHESH EMBROIDERY	Not – Eligible	- Manufacturing License not submitted - UTR no is not	Not – Received	-	-	Fail

S. No	Name of firm/ Supplier	Technically Qualified/ Not qualified	Reason for technical disqualification	Sample submission status	Sample evaluation result	Reason for Sample disqualification	Final result (based on Technical and Sample Evaluation)
			identified				

Managing Director
UPMSCL